

RS LOTO Log Sheet

LTB Remote Enable Key Switch

March 5, 2007

1. Tag Number: 6162 Lock Number: 10L240
2. Component Name/Number: LTB beamstop remote enable key switch
(Bldg. 914)
3. Reason: LOTO pending analysis of fault study results.
4. LOTO Performed by: Chris J. Gardner, 5 March 2007.
5. Special Locking and Tagging Instructions (None).
6. Independent Verification Required? (No)
7. During operating periods, Operations Coordinator is notified for
placement.
8. Special Removal Instructions (None).
9. RS LOTO Removed by (sign and date):